

Technical Data Sheet

Urethane Windshield Adhesive is a one part moisture curing urethane adhesive designed to provide a strong bond to all windshield and backlight replacements. This product exhibits excellent adhesion to glass and pinchweld surfaces designed for use in a close cut-out method or tape installation. Urethane Windshield Adhesive passes FMVSS 212 strength requirements.

MIXING



By Volume: Ready to use

FLASH TIMES/DRY TIMES



25 minutes @ 73°F (23°C), 50% RH and 3 mm thickness Skin time: 2 hours @ temps between 23°F (-5°C) and 104°F (40°C) Drive away time: Cure through time: 24 hours @ 73°F (23°C), 50% RH and 3 mm thickness

SURFACE PREPARATION



Cleaning: Clean with glass cleaner. Use Acry Solvent 9783/9784 to clean bonding surface around perimeter of glass.

APPLICATION

Close Cut-Out Method:

- 1. Clean the new windshield with glass cleaner and dry with a clean, lint free cloth.
- 2. Apply Transtar Acry Solvent 9783/9784 to clean bonding surface around perimeter of glass. Allow 5 minutes to flash and dry off.
- 3. Apply a thin coat of Pinchweld Primer over black ceramic band (frit). Allow to dry.
- 4. Remove the old windshield cutting as close to the glass as possible.
- 5. Trim away high spots off the original adhesive. Clean the remainder of original adhesive with a dry brush or compressed air.

Note: Transtar urethanes are primerless to the original urethane. Use Pinchweld Primer on any exposed bare or painted metal.

- 6. Gun a bead of 4502 Urethane Windshield Adhesive directly on the existing bed of urethane.
- 7. Install windshield, applying even pressure on the bond line to assure uniform contact with the adhesive.
- 8. Apply additional adhesive if required. Tool urethane around the edge and replace the molding.
- 9. Clean up with Transtar Acry Solvent 9783/9784.

Full Cut-Out Method:

- 1. Clean the new windshield with glass cleaner and dry with a clean, lint free cloth.
- 2. Wipe with a thin coat of Acry Solvent 9783 to the bonding surface around the edge of the windshield. Allow 5 minutes dry time.
- 3. Remove all but a 1/16" 1/8" layer of the original adhesive from the pinchweld. Clean the old urethane with Acry Solvent 9783/9784.
- 4. Apply butyl tape to the inside edge of the pinchweld, pressing to assure complete contact with the surface before removing the release liner.
- 5. Apply a bead of 4502 Urethane Windshield Adhesive behind the tape. The bead should be slightly higher than the profile of the dam tape.
- 6. Install the windshield making sure to apply even pressure on the bond line to ensure contact with the adhesive.
- 7. Additional urethane can be applied if necessary. Tool urethane around the edge of the windshield and replace the molding.
- 8. Use Acry Solvent 9783/9784 to clean excess urethane.

NOTE: For maximum adhesion protection, windshields that have a black ceramic band will require priming with Pinchweld Primer.

LIMITATIONS & PRECAUTIONS

- For use only by professional, trained painters. Not for sale to or use by the general public.
- Before use, read and follow all TDS, label and SDS precautions.



Technical Data Sheet

PRODUCT TYPICAL PROPERTIES

Color: Black Size: 10.5 fl oz metal cartridge (310 ml), 12/case

RTU Solids: 100%

Tensile Strength: 1740 psi Hardness: Shore A 57 Elongation at Break: 700% Shelf Life: 1 year when stored between 50°F (10°C) and 77°F (25°C) in a cool dry place. The storage temperature sould not exceed 77°F (25°C) for extended periods of time. Keep away from wet areas, direct sunlight and heat sources.

REGULATORY

Category: Adhesive			
VOC Actual	0.03#/gal (4 g/l)	Weight % of Exempt Compounds	0
VOC Regulatory	0.03#/gal (4 g/l)	Volume % of Exempt Compounds	0
Weight % of Volatiles	<0.3%	Density of Material #/gal	10.3
Weight % of Water	0		