Product Name: MSX Super Seam Sealer

Product identifier: 100825 Revision Date: 08-18-2016

Replaces:



1. Identification

Product identifier used on the label:

Product Name: MSX Super Seam Sealer

Product identifier: 100825

Other means of identification

Synonyms: No data available

Recommended use of the chemical and restrictions on

Adhesive & Sealant

use:

Name, address, and telephone number of the chemical manufacturer, importer, or other responsible party

Chemical Manufacturer / ITW Evercoat

Importer / Distributor: a division of Illinois Tool Works Inc.

6600 Cornell Road Cincinnati, OH 45242

513-489-7600

Emergency phone number: CHEMTREC: 1-800-424-9300

CANUTEC: 1-613-996-6666

2. Hazard(s) identification

Classification of the chemical in accordance with paragraph (d) of §1910.1200;

GHS Hazard Symbols:



GHS Classification: Carcinogenicity Category 2

Flammable Liquid Category 4

GHS Signal Word: Warning

GHS Hazard Statements: Combustible Liquid

Suspected of causing cancer.

GHS Precautionary Statements:

Safety Precautions: Obtain special instructions before use.

Do not handle until all safety precautions have been read and understood. Keep away from heat/sparks/open flames/hot surfaces. – No smoking. Wear protective gloves/protective clothing/eye protection/face protection.

First Aid Measures: IF exposed or concerned: Get medical advice/attention.

Page 1 of 7

Product Name: MSX Super Seam Sealer

Product identifier: 100825 **Revision Date:** 08-18-2016

Replaces:

In case of fire: Use appropriate media to extinguish.

Storage: Store in a well-ventilated place. Keep cool.

Store locked up.

Disposal: Dispose of contents/container in accordance with

local/regional/national/international regulation for hazardous wastes.

Hazards not otherwise

classified:

No data available

3. Composition/information on ingredientsChemical Component:CAS number and other unique identifiers% (or range) of ingredientTitanium dioxide13463-67-70.1 - 1

The specific chemical identity and/or exact percentage (concentration) of composition has been withheld as a trade secret.

4. First-aid measures

Description of necessary measures, subdivided according to the different routes of exposure, i.e., inhalation, skin and eye contact, and ingestion:

Eye Contact: Use an eye wash to remove a chemical from your eye regardless of

the level of hazard. Flush the affected eye for at least twenty minutes. Tilt the head to prevent chemical from transferring to the

uncontaminated eye. Seek medical advice after flushing. Immediately flush with plenty of water. After initial flushing, remove any contact lenses and continue flushing for at least 15 minutes. Have eyes examined and tested by medical personnel.

Skin Contact: Wash with soap and water. Get medical attention if irritation

develops or persists.

Inhalation: Remove to fresh air. If breathing is difficult, have a trained

individual administer oxygen.

Ingestion: Minimal risk of harm if swallowed. Do not induce vomiting. Seek

medical attention immediately. Provide medical care provider with

this MSDS.

Most important symptoms/effects, acute and delayed:

Most important No data available

symptoms/effects (Acute):

Most important No data available

symptoms/effects (Delayed):

Indication of immediate medical

attention and special treatment

needed, if necessary:

No additional first aid information available

Product Name: MSX Super Seam Sealer

Product identifier: 100825 **Revision Date:** 08-18-2016

Replaces:

5. Fire-fighting measures

Suitable (and unsuitable) extinguishing media:

Suitable extinguishing media: Use alcohol resistant foam, carbon dioxide, dry chemical, or water

> spray when fighting fires. Water or foam may cause frothing if liquid is burning but it still may be a useful extinguishing agent if carefully applied to the fire. Do not direct a water stream directly

into the hot burning liquid.

No data available Unsuitable extinguishing media:

Specific hazards arising from the chemical (e.g., nature of any hazardous combustion products):

Fire and/or Explosion Material may be ignited if preheated to temperatures above the

Hazards: flash point in the presence of a source of ignition.

Hazardous Combustion Carbon dioxide. Carbon monoxide

Products: Special protective equipment

and precautions for fire-

fighters:

Do not enter fire area without proper protection including selfcontained breathing apparatus and full protective equipment. Fight

fire from a safe distance and a protected location due to the potential of hazardous vapors and decomposition products.

6. Accidental release measures

Personal precautions, protective equipment, and emergency procedures: Methods and materials for

No health affects expected from the clean-up of this material if contact can be avoided. Follow personal protective equipment

recommendations found in Section VIII of this MSDS

No special spill clean-up considerations. Collect and discard in containment and cleaning up:

regular trash.

7. Handling and storage

Precautions for safe handling: Mildly irritating material. Avoid unnecessary exposure.

Conditions for safe storage, including any incompatibilities

Conditions for safe storage:

Materials to Avoid/Chemical

Incompatibility:

Store in a cool dry place. Isolate from incompatible materials.

Acids Aluminum alloys Ammonia Metals

Product Name: MSX Super Seam Sealer

Product identifier: 100825 Revision Date: 08-18-2016

Replaces:

8. Exposure controls/personal protection

OSHA permissible exposure limit (PEL), American Conference of Governmental Industrial Hygienists (ACGIH) Threshold Limit Value (TLV), and any other exposure limit used or recommended by the chemical manufacturer, importer, or employer preparing the safety data sheet, where available:

Chemical Component	OSHA PEL	ACGIH TLV-TWA	ACGIH STEL	
Titanium dioxide	15 mg/m3	10 mg/m3	No data available	

Appropriate engineering

controls:

No exposure limits exist for the constituents of this product. General room ventilation might be required to maintain operator comfort under normal conditions of use. Engineering controls must be designed to meet the OSHA chemical specific standard in 29 CFR 1910. Use process enclosures, local exhaust ventilation, or other

engineering controls to control airborne levels below

recommended exposure limits

Individual protection measures, such as personal protective equipment:

Eye Protection: Wear safety glasses when handling this product. Wear goggles if

dusts can reach the exposure limit.

Skin Protection: Not normally considered a skin hazard. Where use can result in skin

contact, practice good personal hygiene and wear a barrier cream and/or impervious surgical style gloves. Wash hands and other exposed areas with mild soap and water before eating, drinking,

and when leaving work.

Respiratory Protection: No respiratory protection required under normal conditions of use.

Provide general room exhaust ventilation if symptoms of overexposure occur as explained Section III. A respirator is not normally required. Follow a respiratory protection program that meets 29 CFR 1910.134 and ANSI Z88.2 requirements whenever work place conditions warrant the use of a respirator. Respiratory protection may be required in addition to ventilation depending

upon conditions of use.

Other Protective Equipment: Wear goggles if dusts can reach the exposure limit.

9. Physical and chemical properties

Appearance (physical state, color, etc.):

Appearance (physical state): Paste Color: Tan

Odor:

Odor threshold:

PH:

No data available

Initial Boiling Point and Boiling Range (°C): 825 Flash Point (°C): 93

Product Name: MSX Super Seam Sealer

Product identifier: 100825 **Revision Date:** 08-18-2016

Replaces:

Evaporation Rate: No data available Flammability (solid, gas): No data available

Upper/lower flammability or explosive limits:

Upper Flammable/Explosive Limit (%): No data available Lower Flammable/Explosive Limit (%): No data available **Vapor Pressure:** No data available Vapor Density: No data available **Relative Density:** Not determined Solubility(ies): Minimal: 1-9% Partition coefficient: n-octanol/water: No data available **Auto-ignition Temperature (°C):** No data available **Decomposition Temperature:** No data available Viscosity: No data available

10. Stability and reactivity

Reactivity: No data available

Chemical stability: Stable under normal conditions.

Possibility of hazardous No data available

reactions:

Conditions to avoid (e.g., static

discharge, shock, or vibration):

Incompatible materials: **Hazardous decomposition**

products:

Contamination

Acids Aluminum alloys Ammonia Metals Carbon dioxide, Carbon monoxide

11. Toxicological information

Information on the likely routes Inhalation, Ingestion, Skin contact, Eye contact

of exposure (inhalation,

ingestion, skin and eye contact):

Symptoms related to the physical, chemical and

toxicological characteristics:

No data available

Delayed and immediate effects and also chronic effects from short- and long-term exposure:

Immediate (Acute) Health Effects by Route of Exposure:

Inhalation Irritation: Can cause minor respiratory irritation, dizziness, weakness, fatigue, nausea, and

Inhalation Toxicity: Harmful! Can cause systemic damage (see "Target Organs) Can cause minor skin irritation, defatting, and dermatitis. Skin Contact:

Eye Contact: Can cause minor irritation, tearing and reddening. Can cause mechanical irritation if

dusts are generated.

Mildly irritating to mouth, throat, and stomach. Can cause abdominal discomfort. **Ingestion Irritation:**

Product Name: MSX Super Seam Sealer

Product identifier: 100825 **Revision Date:** 08-18-2016

Replaces:

Ingestion Toxicity:

Long-Term (Chronic) Health Effects:

Carcinogenicity: Suspected of causing cancer.

Reproductive andNo data available to indicate product or any components present at greater than

Developmental Toxicity: 0.1% may cause birth defects.

Mutagenicity:No data available to indicate product or any components present at greater than

0.1% is mutagenic or genotoxic.

Inhalation: Upon prolonged and/or repeated exposure, can cause minor respiratory irritation,

dizziness, weakness, fatigue, nausea, and headache. Harmful! Can cause systemic

damage upon prolonged and/or repeated exposure (see "Target Organs)

Skin Contact: Upon prolonged or repeated contact, can cause minor skin irritation, defatting, and

dermatitis.

Numerical measures of toxicity (such as acute toxicity estimates)

Component Toxicology Data

Chemical Component	Oral LD50	Dermal LD50	Inhalation LC50	
No data available				

Whether the hazardous chemical is listed in the National Toxicology Program (NTP) Report on Carcinogens (latest edition) or has been found to be a potential carcinogen in the International Agency for Research on Cancer (IARC) Monographs (latest edition), or by OSHA

Chemical Name	OSHA Carcinogen	IARC Carcinogen	NTP Carcinogen	
Titanium dioxide	N	Υ	N	

12. Ecological information

Ecotoxicity (aquatic andThis material is not expected to be harmful to the ecology.

terrestrial, where available):

Persistence and degradability: No data available

Bioaccumulative potential: No data

Mobility in soil: No data available

Other adverse effects (such as No data available

hazardous to the ozone layer):

Ecological Toxicity Data

Chemical Component	Aquatic EC50 Crustacea	Aquatic ERC50 Algae	Aquatic LC50 Fish	
Titanium dioxide	Aquatic EC50 (48h)		Aquatic LC50 (96h) >	
	Daphnia > 1000 ml/l		1000 MG/L	

Product Name: MSX Super Seam Sealer

Product identifier: 100825 Revision Date: 08-18-2016

Replaces:

13. Disposal considerations

Description of waste residues and information on their safe handling and methods of disposal, including the disposal of any contaminated packaging

Description of waste residues: Spent or discarded material may be a hazardous waste. **Waste treatment methods** Dispose of by incineration following Federal, State, Local, or

(including packaging): Provincial regulations.

14. Transport information

UN number:

UN proper shipping name:

Transport hazard class(es):

Packing group:

No data available

No data available

The shipper is responsible for following all applicable regulations. The transportation classification provided is based on ITW Evercoat original packaging, which is suitable for domestic ground transport only.

15. Regulatory information

Safety, health and environmental regulations specific for the product in question

TSCA Status: All components in this product are on the TSCA Inventory.

Regulated Components

Chemical Component	CAS number and other unique identifiers	CERCLA	SARA EHS	SARA 313	California Prop 65
Titanium dioxide	13463-67-7	N	N	Υ	Υ
Carbon black	1333-86-4	N	N	N	Υ

16. Other information, including date of preparation or last revision.

Revision Date: 08-18-2016

Revision Number: 8

Disclaimer: NOTICE: The information accumulated herein is believed to be correct as of the date issued from sources, which are believed to be accurate and reliable. Since it is not possible to anticipate all circumstances of use, recipients are advised to confirm, in advance of need, that the information is current, applicable and suitable to their circumstances